



Asbestos Assessor:	Agon Enviro	Asbestos Status:	No ACM Detected - Consult	Overall Risk Rating:	0 - Not Applicable
--------------------	-------------	------------------	---------------------------	----------------------	--------------------

EPENARRA HEALTH CENTRE-WUTUNUGURRA 02022



Location Details		Material Details		Results / Management Details		Photographs
ID/Primary Location:	2564 - 02 AGI Hearing Booth	Material Type:	-	Status of ACM:	-	
Elevation:	Ground Floor	Quantity:	1	Sample ID:		
Position Installed:	-	Condition:	-	Sample Result:	-	
Secondary Location:	-	Friability:	-	Risk Rating:		
Urgent Action Required:	No	Surface Treatment:	-	Recommendation:	-	
Comments:	No asbestos or ACM visible upon inspection.					

Location Details		Material Details		Results / Management Details		Photographs
ID/Primary Location:	2565 - Main Building	Material Type:	-	Status of ACM:	-	
Elevation:	Ground Floor	Quantity:	1	Sample ID:		
Position Installed:	-	Condition:	-	Sample Result:	-	
Secondary Location:	-	Friability:	-	Risk Rating:		
Urgent Action Required:	No	Surface Treatment:	-	Recommendation:	-	
Comments:	No asbestos or ACM visible upon inspection.					